

Instruction Sheet for Thermal Fuse Replacement Kit LA-1053

Replacement for Maytag



WARNING!
Electrical Shock Hazard

To avoid risk of electrical shock, personal injury or death; disconnect electrical power before servicing.



Contents:

- (1) **53-1182** Thermal Fuse
small unit with PINK DOT on body
- (1) **53-1096** High Limit Thermostat - Gas Model
small unit with YELLOW DOT on body
- (1) **53-0771** High Limit Thermostat - Electric Model
large unit with BLUE DOT on body

The purpose of this kit is to provide the parts necessary to properly replace an open thermal fuse on either an electric or gas model dryer.

The kit not only provides a replacement thermal fuse, but also two high limit thermostats; one for electric model dryers and one for gas models. The same thermal fuse is used on both models.

After correcting the dryer malfunction which caused the thermal fuse to open, be sure to replace the high limit thermostat as well as the thermal fuse. This is necessary since the high limit thermostat is designed to open at a lower temperature than the thermal fuse, and failed to do so.

Note: As an additional precaution, check the total exhaust system (lint filter, vent duct, vent hood) for lint build-up and clean as necessary